




AM 2118B


SCREW LIST

A	M8*16		7
B	M5		1
C			
D			
E			
F			
G			
H			
J			


A




B



C





D




E

AM 2118B


SCREW LIST

A	M8*16		7
B	M5		1
C			
D			
E			
F			
G			
H			
J			


A




B



C



D



E